

Date	ExecBlock	PWV [mm]	Band	Source	Longest Baseline	Flagged Antenna	Note
10–15 km baseline data							
	uid://A002/X8ba346/Xae6	2.25					DV19 could be problems with phase jumps.
2014/9/9	uid://A002/X8b5a69/Xd3	1.63571	3	2253+1608	DA50–DV19: 9207 m		
	uid://A002/X8b5a69/X233	1.45499	7	2253+1608	DA50–DV19: 9207 m		
2014/9/12	uid://A002/X8ba346/X9bb	1.89341	3	0428–3756	DA41–DV19: 8283 m	DV14	DV14 pad position is not determined yet.
2014/9/13	uid://A002/X8bc8aa/X962	2.5271	3	0522–364	DA41–DV19: 8283 m	DV14	Very random in phase, although can see amplitude. After WVR correction is OK. DV14 pad position is not determined yet.
	uid://A002/X8bc8aa/X9b5	3.50372	6	0522–364		DV14	Very random in raw phase. First several minutes, WVR correction works, but after that, no effect. Amplitude jumps around after first several minutes, too. Probably clouds crossing. DV14 pad position is not determined yet.
2014/9/14	uid://A002/X8bd3e8/Xa59	0.610708	3	0522–364	DA43–DA50: 9538 m	DV14	DV14 pad position is not determined yet.
	uid://A002/X8bd3e8/Xac6	0.56938	6	0522–364	DA43–DA50: 9538 m	DV14	DV14 pad position is not determined yet.
	uid://A002/X8bd3e8/Xc55	0.551341	7	0522–364	DA43–DA50: 9538 m	DV11, DV14, DV15	DV14 pad position is not determined yet. DV11 & DV15 are not integrated yet.
2014/9/15	uid://A002/X8beb08/Xe43	0.952752	3	0522–364	DA43–DA50: 9538 m	DV08, DV14	DV08 & DV14 pad positions are not determined yet.
	uid://A002/X8beb08/Xea2	0.983236	7	0522–364	DA43–DA50: 9538 m	DV08, DV14	DV08 & DV14 pad positions are not determined yet.
2014/9/16	uid://A002/X8c0e65/Xc72	0.770725	3	0522–364	DA43–DA50: 9538 m		
	uid://A002/X8c0e65/Xe16	0.795002	6	0522–364	DA43–DA50: 9538 m	DV25	DV25 shows a phase jump at the first scan.
	uid://A002/X8c0e65/X1151	0.750892	7	0522–364	DA43–DA50: 9538 m		There is a scan gap when phase drift was huge, so that the phase wrapping does not work well. Result is therefore not that
2014/9/23	uid://A002/X8d054c/X276	2.12544	3	3C454.3	DA50–DV13: 10855 m	DV01, DV09	DV01 EL encoder failure. DV09 unlock.
	uid://A002/X8d054c/X99b	1.95381	6	3C454.3	DA50–DV13: 10855 m	DA57	Very random in phase, although can see amplitude. After WVR correction is OK. DA57 receiver problem (unstable amplitude).
	uid://A002/X8d054c/Xaf4	1.87289	7	3C454.3	DA50–DV13: 10855 m		Very random in phase, although can see amplitude. After WVR correction is OK.
2014/9/26	uid://A002/X8d8bc2/Xe5	1.14837	3	1924–292	DA50–DV13: 10855 m		
	uid://A002/X8d8bc2/X125	1.04835	6	1924–292	DA50–DV13: 10855 m		
	uid://A002/X8d8bc2/X165	1.04446	7	1924–292	DA50–DV13: 10855 m		
2014/9/28	uid://A002/X8da59e/X5	1.48153	3	1924–292	DA50–DV13: 10855 m		DA41 BBO has an amplitude jump.
	uid://A002/X8da59e/X45	1.36696	6	1924–292	DA50–DV13: 10855 m	DA57?	Very random in phase, although can see amplitude. After WVR correction is OK. DA57 polX problem? (2015/1/7)
	uid://A002/X8da59e/X85	1.53515	3	1924–292	DA50–DV13: 10855 m		
2014/9/29	uid://A002/X8dd2a4/Xae7	0.593237	8	0522–364	DA50–DV13: 10855 m		
	uid://A002/X8dd2a4/Xd	1.79					Delay jumps at mid point in time.
	uid://A002/X8dd128/X2b	0.999174	3	3C279	DA41–DV19: 8283 m		DA41 BBO has no power.
	uid://A002/X8dd128/X6c	1.08					Delay jump in DV15–DV25 only
2014/10/1	uid://A002/X8e1004/Xec4	0.531954	3	0522–364	DA50–DV13: 10855 m		
	uid://A002/X8e1004/Xf04	0.531503	6	0522–364	DA50–DV13: 10855 m	DV17	DV17 unlocked in the middle of the observation.
	uid://A002/X8e1004/Xf44	0.523664	7	0522–364	DA50–DV13: 10855 m		
	uid://A002/X8e1004/Xfe5	0.46468	8	0522–3627	DA50–DV13: 10855 m		
	uid://A002/X8e1004/X1108	0.447341	9	0522–364			Need more S/N.
2014/10/5	uid://A002/X8ec7bb/X1123	0.328574	3	0522–364	DV13–DV19: 10657 m		

	uid://A002/X8ec7bb/X1755	0.271883	9	1058+015			Cannot see any fringes, both in amplitude and phase, even after the WVR phase correction...
2014/10/29	uid://A002/X91bdc6/X36	1.93573	3	3C454.3	DA50-DA55: 12457 m		
	uid://A002/X91bdc6/X8	1.83					DV21 delay jump and noise issue.
2014/10/30	uid://A002/X91cc20/X8f	0.652112	3	3C454.3	DV07-DA55: 15238 m	DV21, DA42	DV21 & DA42 have no signal.
2014/11/1	uid://A002/X920302/X1d6d	1.33257	3	1924-292	DV07-DA55: 15238 m		
3 km baseline data							
2013/6/3	uid__A002_X65a644_Xd	0.681319	3	1058+015	DV19-DV24: 2733 m	DV23, DV25	DV15 WVR problem. DV23 no signal, WVR problem.
2013/6/6	uid__A002_X660b54_Xae2	0.544142	3	NRAO530	DV19-DV24: 2733 m	DV01, DV23	DV01 no signal. DV15 WVR problem. DV23 no signal, WVR
2013/6/6	uid__A002_X660b54_X16de	0.54565	3	1924-292	DV19-DV24: 2733 m	DA58, DV01, DV23	DA58 no signal. DV01 no signal. DV15 WVR problem. DV23 no signal, WVR problem.
2013/6/6	uid__A002_X660b54_X1caf	0.545275	3	2348-165	DV19-DV24: 2733 m	DA51, DA58, DV01, DV23	DA51 no signal. DA58 no signal. DV01 no signal. DV15 WVR problem. DV23 no signal, WVR problem.
2013/6/6	uid__A002_X660b54_X1d7e	0.544381	6	2348-165	DV19-DV24: 2733 m	DA51, DA58, DV01, DV23	DA51 no signal. DA58 no signal. DV01 no signal. DV15 WVR problem. DV23 no signal, WVR problem.
2013/6/6	uid__A002_X660b54_X1f3c	0.570997	7	2348-165	DV19-DV24: 2733 m	DA51, DA58, DV01, DV23	DA51 no signal. DA58 no signal. DV01 no signal. DV03 WVR problem? DV15 WVR problem. DV23 no signal, WVR problem.
2013/6/7	uid__A002_X6643c8_X3e6	1.46451	3	1924-292	DV19-DV24: 2733 m		DV15 WVR problem. DV23 WVR problem.
2013/6/7	uid__A002_X6643c8_X425	1.41776	6	1924-292	DV19-DV24: 2733 m		DV15 WVR problem. DV23 WVR problem.
2013/6/7	uid__A002_X6643c8_X47d	1.39216	7	1924-292	DV19-DV24: 2733 m		DV15 WVR problem. DV23 WVR problem.
2 km baseline data							
2012/5/2	uid__A002_X3f4b85_X392	1.54094	6	1924-292	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/2	uid__A002_X3f4b85_X399	1.64638	6	1924-292	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/10	uid__A002_X3ffc69_X71	0.975017	6	3C279	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/10	uid__A002_X401024_Xca	0.862981	6	2258-279	DV17-PM03: 2287 m	DV09, DV15	DV15 WVR problem.
2012/5/10	uid__A002_X401c5a_X13e	1.95839	3	0522-364	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/11	uid__A002_X403046_X3d	1.77728	3	1924-292	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/12	uid__A002_X404191_X26	1.91231	3	3C279	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/12	uid__A002_X4056cb_X3ac	1.13626	3	3C454.3	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/12	uid__A002_X4056cb_X3b3	1.29528	7	3C454.3	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/15	uid__A002_X40b03b_X2c	1.68891	3	3C279	DV07-PM03: 2254 m	DV15	DV15 WVR problem.
2012/5/15	uid__A002_X40b03b_X36c	1.56407	3	3C279	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/15	uid__A002_X40b03b_X465	1.46499	3	3C279	DV17-PM03: 2287 m	DV15	DV15 WVR problem.
2012/5/15	uid__A002_X40c17a_X120	0.685479	3	3C454.3	DV17-PM03: 2287 m	DV03, DV15	DV15 WVR problem.
2012/5/26	uid__A002_X412ad5_X5dd	1.97183	3	1924-292	DV17-PM03: 2287 m		